


Attachment 15: Photographs of the Severely Distressed Housing Milwaukee, WI

Milwaukee_WI_Attachment_15.pdf



Outdated electrical system.




Mold.




Large inefficient duplex.



Distressed shed.



Distressed basement electric, doesn't meet current building standards.




Distressed bathroom. Inaccessible—needs total replacement.


HOPE VI
Attachment 15
Photographs of Physical Distress



Duplex is not accessible.



Failing brick foundation.



Failing brick foundation.



Hazardous kitchen with burn marks on the wall.




Small house with too many steps (inaccessible).



Mixed materials foundation repaired over many years.


HOPE VI
Attachment 15
Photographs of Physical Distress




Severe mold on wall.



No accessibility.




Old inefficient furnace.



Old inefficient hot water heater.




Old plumbing and rotting floors.




Patched front porch.


HOPE VI
Attachment 15
Photographs of Physical Distress




Rusting ductwork.



Small house, inaccessible and too dense.



Too many renovations, entrance near back of house.



Uninsulated attic.